

---

# DET NORSKE VERITAS

---

## MANAGEMENT SYSTEM CERTIFICATE

---

Certificate No. 11664-2006-AQ-ROT-UKAS

*This is to certify that*

**Rockwell Automation Ltd.**

*has been found to conform to the Management System Standard:*

**ISO 9001:2000 + TickIT**

*This Certificate is valid for the following product or service ranges:*

**Engineering, Sales and support of Products,  
Systems and Services for Industrial Automation.**

*Initial Certification date:*  
24 September 2006

---

*Place and date:*  
Antwerp, 13 October 2006

---

*This Certificate is valid until:*  
24 September 2009

---



*The audit has been performed under the supervision of:*  
H.J.M. Degryse  
*Lead Auditor*

---

*for the Accredited Unit:*  
DNV Certification B.V.,  
The Netherlands

---

*Luc Larmuseau*  
Management Representative

---

Lack of fulfillment of conditions as set out in the Appendix may render this Certificate invalid.



---

# DET NORSKE VERITAS

---

## MANAGEMENT SYSTEM CERTIFICATE

---

Certificate No. 11663-2006-AQ-ROT-RvA

*This is to certify that*

### **Rockwell Automation EMEA Sales and Support**

*has been found to conform to the Management System Standard:*

**ISO 9001:2000**

*This Certificate is valid for the following product or service ranges:*

**Engineering, Sales & Support of Products,  
Systems and Services for Industrial Automation.**

*Initial Certification date:*  
24 September 2006

---

*Place and date:*  
Antwerp, 13 October 2006

---

*This Certificate is valid until:*  
24 September 2009

---




*for the Accredited Unit:*  
DNV CERTIFICATION B.V.,  
The Netherlands

*The audit has been performed under the supervision of:*

---

H.J.M. Degryse  
*Lead Auditor*

  
Luc Larmuseau  
*Management Representative*

---

Lack of fulfilment of conditions as set out in the Appendix may render this Certificate invalid.



Addendum Certificate No. 11664-2006-AQ-ROT-UKAS  
Certified sites Rockwell Automation Ltd.

Rockwell Automation Limited  
Pitfield  
Kiln Farm  
Milton Keynes  
MK11 3DR  
United Kingdom

Rockwell Automation Limited  
MPS Application Centre  
Denbigh Road  
Bletchley  
Milton Keynes  
MK1 1EP  
United Kingdom

Rockwell Automation Limited  
Swords Business Campus  
Balheary Road  
Swords  
Dublin  
Ireland



Addendum Certificate No. 11663-2006-AQ-ROT-RvA  
Certified sites Rockwell Automation EMEA Sales & Support

**Benelux:**

Rockwell Automation B.V.  
European Shared Services Center  
Communicatieweg 5  
2909 LE Capelle aan den IJssel  
The Netherlands

Rockwell Automation B.V.  
Rivium 1e straat 23  
3641 SG Mijdrecht  
The Netherlands

Rockwell Automation SA/NV  
Nijverheidslaan 1 - Orion Park II  
1853 Strombeek  
Belgium

**Scandinavia:**

Rockwell Automation A/S  
Herstedøstervej 27-29 J  
2620 Albertslund  
Denmark

Rockwell Automation AB  
Drakegatan 6, 9. th fl.  
412 50 Göteborg  
Sweden

**Italy:**

Rockwell Automation S.r.l.  
Via Gallarate, 215  
20151 Milano

**France & Iberia:**

Rockwell Automation SAS  
2, rue René Caudron  
78 960 Voisins-le-Bretonneux  
France

Rockwell Automation SA  
Doctor Trueta 113-119  
Edificio A  
Barcelona 08005  
Spain

Rockwell Automation Lda  
Av. Prof. Dr. Cavaco Silva  
Tagus Park Edificio Ciencia II No 11-2 C  
Porto Salvo 2740-120  
Portugal

Rockwell Automation SAS  
95, Boulevard Abdel Moumen  
20 100 Casablanca  
Casablanca Marocco

**CEE:**

Rockwell Automation s.r.o.  
Pekarska 695a/16  
155 00 Praha 5  
Czech Republic

Rockwell Automation Services s.r.o.  
Havlickova 822  
280 00 Kolin  
Czech Republic

**Additional scope : Production of electrical equipment**

Rockwell Automation Slovakia s.r.o.  
Samorinska 10  
821 06 Bratislava  
Slovak Republic

Rockwell Automation Sp. z o.o.  
Ul. Powazkowska 44c  
01-797 Warsaw  
Poland

**DACH:**

Rockwell Automation  
Zweigniederlassung der Rockwell International GmbH  
Duesselberger Straße 15  
42781 Haan  
Germany

Rockwell Automation GmbH  
Kotzinastraße 9  
4030 Linz  
Austria

Rockwell Automation AG  
Hintermaettlistaraße 3  
5506 Maegenwil  
Switzerland

Lack of fulfilment of conditions as set out in the Appendix may render this Certificate invalid.